

# **GREEN CHEM**

LABORATORIES

# BIG O

FRESH ORANGE SCENT

## ORGANIC DEGREASER AND ADHESIVE REMOVER 93% ACTIVE INGREDIENT







REMOVES



REMOVES ASPHALT & TAR



SAFE ON MOST SURFACES

**KEEP OUT OF REACH OF CHILDREN. DANGER:** Extremely flammable aerosol.contains gas under pressure; may explode if heated.









**BIG 0** contains all natural d-limonene, which is derived from orange peel extract This product will remove heavy duty buildup, grease, tar, asphaslt and adhesive from a variety of surfaces.

### DIRECTIONS

Read entire label before use and follow all directions. Use in well-ventilated areas. Hold the can 8 - 12 inches from surface. Spray directly onto surface to be treated. Let set for several seconds. Wipe off or flush clean with water.

NOTE: BIG O may be harmful to plastics or painted surfaces. Always test surface in an inconspicuous area before using. Because BIG O is a powerful grease solvent, it will defat skin. When using BIG O, rubber gloves are recommended to avoid chapped skin. Do not spray into or on electrical equipment.

### CAUTION

Use with adequate ventilation. Intentional misuse by concentrating and inhaling the product can be harmful.

#### DANGER

Extremely Flammable Aerosol. Contains gas under pressure; may explode if heated. Causes skin and serious eye irritation. May cause an allergic skin reaction. Keep away from heat, sparks, open flames, and hot surfaces. -No smoking. Do not spray on an open flame or other ignition source. Pressurized container: Do not pierce or burn, even after use. Protect from sunlight. Do not expose to temperatures exceeding 50°C/122°F.





Store in a well-ventilated place. Wash hands thoroughly after handling. Wear protective gloves and eve protection.

IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: Get medical attention. Avoid breathing vapors/spray. IF ON SKIN: Wash with plenty of soap and water. If skin irritation or rash occurs: Get medical advice/attention. Wash contaminated clothing before reuse. Contaminated work clothing must not be allowed out of the workplace. Dispose of in accordance with local, state, and federal laws.

CONTAINS/CAS NUMBER: d-Limonene (5989-27-5), Carbon Dioxide (124-38-9), Alcohols, C6-C12, ethoxylated propoxylated (68937-66-6), Alcohols, C10-C16, ethoxylated propoxylated (69227-22-1).

HMIS® RATINGS: Health - 1, Flammability- 2, Reactivity- 0, Personal Protection - B.

For industrial and commercial use only.
See Safety Data Sheet for complete safety information.
24 HOUR MEDICAL EMERGENCY 1-866-836-8855

Green Chem Laboratories • www.GreenChemLabs.com • 1-800-964-3151