



THE STRUGGLE

Oh no! #2 Heating Oil dripped down the walls...





THE FIX

Biggie to the rescue!! We simply sprayed Biggie on the #2 Heating Oil, and wiped it off with our Wicked Wipes. You can see that it did not affect the paint.









MADE IN America BIGGIE Approved

www.GreenChemLabs.com · 1-800-964-3151









THE STRUGGLE

Oh no! Someone left a trail of ink from an industrial printer on the hand rail...



BIGGIE

THE FIX

Biggie to the rescue! We sprayed Biggie on the ink and it just melted it away and did not damage the paint.












ENVIRONMENTALLY WOMAN OWNED RESPONSIBLE SMALL BUSINESS

MADE IN America BIGGIE Approved

www.GreenChemLabs.com · 1-800-964-3151





THE STRUGGLE

Oh no! Our friends in the Biomed department have to remove permanent bar code labels that aren't supposed to ever come off...



۵ 🚳 🚵 ا

THE FIX

Biggie to the rescue! We sprayed Biggie directly on the adhesive and let it sit for 30 seconds. Then we used our Super Scraper to lift the label off without scratching paint.



ENVIRONMENTALLY RESPONSIBLE

WOMAN OWNED SMALL BUSINESS MADE IN America BIGGIE Approved

www.GreenChemLabs.com · 1-800-964-3151